
Tools & Supplies Required for This Procedure:

- #2 Phillips screwdriver
- 5mm Allen wrench

Procedure Steps:

(Before starting, please read instructions all the way through to ensure complete understanding)

- 1. Disconnect all electrical power to the saw.
- 2. Using the #2 Phillips screwdriver, remove the 7 screws from the left side of the switch box, and pull the left side cover off the switch box. Set it aside, taking care not to lose any screws.
- 3. Unplug the two cables from the switch box circuit board; loosen the strain relief bar to allow the cables to be removed from the switch box.



- 4. Using the 5mm Allen wrench, remove the four 5mm mounting screws and dismount the switch box from its mounting bracket.
- 5. Install the new switch box on the saw, reversing steps 1 4 above. Make sure when reinstalling the strain relief bar that you don't crush the power cable and cartridge cable.

Rev: 1/4/2011 Page 1 of 1